

检测报告
Test Report

报告编号 A2180054406101001E

第 1 页 共 4 页

Report No. A2180054406101001E

Page 1 of 4

申请单位 广东恒太科技发展有限公司

Applicant GUANGDONG HENTECH TECHNOLOGY DEVELOPMENT CO., LTD.

地址 广东佛山市顺德区勒流街道连杜村天任工业园内(自编)58 号厂房

Address NO. 58 TIANREN INDUSTRIAL ESTATE, LIANDU VILLAGE, LELIU TOWN, SHUNDE DISTRICT FOSHAN CITY, GUANGDONG, CHINA

以下测试之样品及样品信息由申请者提供并确认

The following sample(s) and sample information was/were submitted and identified by/on the behalf of the client

样品名称	HT201(外框及挂板) 样一
Sample Name	HT201(外框及挂板) 样一
材质	316 不锈钢
Material	316 不锈钢
样品接收状态	样品表面有划痕
Sample Receiving State	Scratch was found on the sample surface.
样品接收日期	2018.04.20
Sample Received Date	Apr. 20, 2018
样品检测日期	2018.04.20-2018.04.26
Testing Period	Apr. 20, 2018-Apr. 26, 2018

批准
Approved by

肖业湘

日期
Date2018.04.26
Apr. 26, 2018肖业湘
授权签字人
Approved Signatory
华测检测认证集团股份有限公司No. RE49736E1C
广东省深圳市宝安区 70 区鸿威工业园

检测报告
Test Report

报告编号 A2180054406101001E

第 2 页 共 4 页

Report No. A2180054406101001E

Page 2 of 4

检测要求

Test Requested

序号 No.	测试项目 Test Item
1	中性盐雾试验 Salt spray test

检测结果：请参见后续页面。

Test Result(s): Please see the following pages.



测试样品

Tested Sample(s)

样品编号 Sample No.	样品名称 Sample Name	材质 Material	样品数量 Quantity
A2180054406101001	HT201(外框及挂板) 样一	316 不锈钢	1pc
	HT201(外框及挂板) 样一	316 不锈钢	

样品图片

Sample Photo(s)



检测报告
Test Report

报告编号 A2180054406101001E

第 3 页 共 4 页

Report No. A2180054406101001E

Page 3 of 4

测试项目：中性盐雾试验

Test Item: Salt spray test

1. 测试设备 Test Equipment

设备名称 Equipment Name	型号 Model
盐水喷雾试验箱 Salt Fog Tester	NQ-750

2. 环境条件 Environmental Conditions

温度：24℃； 湿度：63%RH

Temperature: 24℃; Humidity: 63%RH

3. 测试标准 Test Standard: IEC 60068-2-11:1981

4. 测试条件

Test Condition

试验箱温度：35℃

Temperature of the chamber: 35℃

饱和器温度：47℃

Temperature of the saturation tower: 47℃

溶液浓度：5%NaCl（质量比）

Salt solution: 5%NaCl(by weight)

溶液 pH 值：6.7（35℃）

pH of salt solution: 6.7（35℃）

盐雾沉降量：1~2ml/h*80cm²Volume of salt solution collected: 1~2ml/h*80cm²

测试时间：72 小时

Test duration: 72 hours

检测报告
Test Report

报告编号 A2180054406101001E

第 4 页 共 4 页

Report No. A2180054406101001E

Page 4 of 4

5. 测试结果

Test Result(s)

样品编号 Sample No.	测试结果（目视检查） Test result(s) (Visual inspection)
A2180054406101001	样品表面无腐蚀 No corrosion was found on the sample surface.

测试后的样品图片

Sample Photo(s) after the test



*** 报告结束 ***

*** End of Report ***

声明:

Statement:

1. 检测报告无批准人签字、“专用章”及报告骑缝章无效;

This report is considered invalidated without approval signature, special seal and the seal on the perforation;

2. 样品及样品信息由申请者提供, 申请者应对其真实性负责, CTI 未核实其真实性;

The sample(s) and sample information was/were provided by the client who should be responsible for the authenticity which CTI hasn't verified;

3. 本报告检测结果仅对送测样品负责;

The result(s) shown in this report refer(s) only to the sample(s) tested;

4. 未经 CTI 书面同意, 不得部分复制本报告。

Without written approval of CTI, this report can't be reproduced except in full;

5. 如检测报告中的英文内容与中文内容有差异, 以中文为准。

In case of any discrepancy between the English version and Chinese version of the testing reports(if generated), the Chinese version shall prevail.